

PRODUCT SAFETY RECALL

STIHL Limited has issued a product safety recall for BR 800 C-E and BR 800 X backpack blower models due to a possible fan wheel molding defect that could result in the fracture of the fan wheel during operation of the blower. This could pose a potential risk of injury to the operator or bystanders during use.

The defect may be present in BR 800 models with a serial number within the listed ranges.

Material number	Model	Affected serial number range
4283-011-1601	BR 800 C-E Z Magnum	546814154 - 547451772
4283-011-1611	BR 800 X-Z Magnum	546911615 - 547689841

Please check the serial number located on the tag affixed to the shoulder housing, just above the angled blower outlet tube section. If your serial number is within the ranges listed above, please stop using it immediately and bring it back to your servicing STIHL dealer for inspection and, if necessary, replacement of the fan wheel. There is no cost for this inspection and repair. Machines with serial numbers outside this range are not included in the recall.



Certain BR 800 C-E and BR 800 X blowers have been previously inspected by STIHL and marked with a black dot on the serial number label (see image above right). Any BR 800 blower within the serial number ranges listed above and marked with the black dot as shown, is safe to continue using and no further action is required.

We ask for your understanding for this precautionary measure. Please take this action in the interest of your own safety.

If you have any questions please do not hesitate to contact us.